

Tools for the SMARTParcel Workstation

Equipment	Specification	Recommended	Required
Computer	Windows 7 or better		X
Internet	Broadband Internet Connection with web access		X
Label Printer	Label printer with peeler that supports 4 x 2 thermal labels and the EPL2 printer language	USB Zebra GC420d with peeler	X
Inkjet or Laser Printer		(for postal paperwork & reports)	X
Scanner	USB/HID/POS	Honeywell 1910i Honeywell 4800i 2D Scanner with USB cable (no longer available, but may be used)	Optional
Scales	Any scale that support the NCI Serial Protocol and has an RS232 serial interface - (NCI and some Bracknell scales). Any of the USB scales in the Stamps.com Store.	We recommend the 35 lb or 70 lb scale on the Stamps.com Store, as they require no programming and are "plug & play"	Optional